

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

【図2】






FIG. 2

2001-132050

【圖】






~~(美至四萬) 路一 (一六六六) 年~~

Fig. 4

~~図5~~


F 1G.5

UP
↑



84 ← 縫製部

10056289 013000



A diagram showing a 90-degree turn. A horizontal arrow points to the right, labeled 'UP' above it. At the end of this arrow, it turns 90 degrees downward, labeled 'FR' to its right.






FIG. 7



【図8】





FIG. 8

FIG. 8

Fig. 9



【図10】




図 11




Fig. 11

2001-132050